

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

**** Delay Codes Legend ****

W=Whse C=CrSp T=Tag TL=Tool P=Plan
 ** Record Time Daily ** Delays

Step	Job Scope	MN	DY	Safety and Additional Information
1	<p>PROVIDE (TOUCH-UP) PAINT CRAFT SUPPORT FOR THE REMOVAL OF THE TEMPORARY LADDERS THAT WERE INSTALL DURING THE OUTAGE IN UNIT-2.</p> <p>** CONTACT "HOWARD HAMILTON" (x6436) FOR ANY QUESTIONS CONCERNING THIS PROJECT.</p> <p>LOCATION: UNIT-2 BOILER AREA, NORTH SIDE OF BOILER, 7TH AND 8TH FLOORS, AND 5TH AND 6TH FLOORS, EAST.</p> <p>***** JOB SCOPE: *****</p> <p>A. PROVIDE TOUCH-UP PAINTING CRAFT SUPPORT AS NEEDED WHERE THE TEMPORARY LADDERS WERE REMOVED.</p> <p>B. PRIME AS REQUIRED.</p> <p>C. FINISH COLOR SAME AS SURROUNDING STEEL STRUCTURE.</p> <p>D. CLEAN UP AFTER YOURSELF PLEASE.</p> <p>** ADDITIONAL INSTRUCTION BY SUPERVISOR **</p>	1	1	<p>** SAFETY / ENVIRONMENTAL REQUIREMENTS: **</p> <p>A. REVIEW MSDS FOR ANY PAINTS, SOLVENTS, ETC, THAT YOU PLAN TO USE.</p> <p>B. BE AWARE THAT SOME OF THE STAIRWAY AND HANDRAIL BEING FABRICATED "MAY" BE ABLE TO BE PAINTED BEFORE INSTALLATION. CONTACT SUPERVISOR TO HELP DETERMINE WHAT PARTS MAY BE PAINTED AND WHEN THEY MIGHT BE DELIVERED.</p> <p>C. WEAR ALL REQUIRED AND RECOMMENDED PPE</p> <p>***** ADDITIONAL INFORMATION *****</p> <p>A. WELDER CREW 57 (x6853) HAS THE LEAD REPAIR WORK ORDER.</p> <p>B. THE SCAFFOLDING CREW (x6853) HAS A SUB TO PROVIDE CRAFT SUPPORT. CONTACT THEM AFTER YOU HAVE FINISHED TOUCH UP PAINTING THE STRUCTURAL STEEL.</p>

[illegible]

**** IMPORTANT NOTICE ****

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7_032351